

Brazos Mutual Domestic Water Consumers Association

Community Liaison Report

Report Date: February 3, 2026

Activity Period: January 2026

Tank Level Inspections

A total of 22 daily tank level checks were performed during the month of January 2026. System storage levels remained stable throughout the month.

Random Meter Checks

No random meter checks were conducted during this period due to limited homeowner activity within the community.

Well System Updates

A new well pump was installed at Well 1A by Richard Ulibarri. Work began on January 19, 2026, and was completed on January 21, 2026. Following installation, the lower tank level increased by approximately one foot and reached full capacity within a 24-hour period.

Overall system performance improved following the pump replacement, and the water supply continues to remain stable.

Invoice

Invoice Date: February 3, 2026

Service Period: January 2026

Prepared By: Chris Dennison, Community Liaison

Mailing Address: HC 75 Box 161, Chama, NM 87520

Description of Services

Community liaison services including daily tank monitoring, coordination of well system maintenance, communication with contractors, and monthly reporting.

Total Amount Due: \$350.00

Please remit payment in accordance with Association payment procedures.